# NEPAL

## Access Constraints as of 17 August 2017

**THIS MAP IS ONLY INTENDED TO DISPLAY THE PHYSICAL CONDITION OF THE ROADS, BASED ON THE BEST INFORMATION AVAILABLE AT THE TIME OF PUBLICATION. IT DOES NOT ADDRESS ACCESS ISSUES RELATED TO FACTORS OTHER THAN THE ACTUAL PHYSICAL CONDITION OF THE ROAD ITSELF. IT DOES NOT REFLECT THE POLITICAL SITUATION, OR ADDRESS SECURITY ISSUES.**

**THIS MAP NEEDS YOUR HELP**
**IF YOU HAVE UPDATED ACCESS INFORMATION CONCERNING PHYSICAL ROAD CONDITIONS TO CONTRIBUTE PLEASE CONTACT THE LOGISTICS CLUSTER INFORMATION MANAGEMENT OFFICER IN KATHMANDU**

**DISCLAIMER**
**THE INFORMATION DISLAYED ON THIS MAP CAN CHANGE AT ANY TIME DUE TO SUDDEN EVENTS (IE METEOROLOGICAL) THAT MAY IMPACT PHYSICAL ROAD CONDITIONS. THE LOGISTICS CLUSTER CANNOT GUARANTEE THE ACCURACY OR COMPLETENESS OF THE INFORMATION DISPLAYED AND ACCEPTS NO LIABILITY FOR RELIANCE ON THE DATA. PLEASE TAKE CARE TO VERIFY THE INFORMATION BEFORE USE.**

Foot Trail connecting Hindung village is blocked by landslide

Road section between Kathmandu and Bidur is disrupted by Landslide in several places

Mugling-Narayangath Road is disrupted by landslides in several places. Road access is intermittent,high risk to travel.

Narayangath-Butwal road is disrupted by landslides in several places.

Road Section between Butwal and Palpa is operational after landslide been cleared.

Vehicular movement along the Pasang Lhamu Highway has been obstructed due to landslide at Ramche

Road section between Barabise and Yarsa is damaged in several locations, one way traffic movement is in operation.

East West Highway has been obstructed due to landslide at Daunne. Diversion road constructed for one way vehicular movement.

Road section between Kathmandu and Hetauda via Daman is closed due to Landslide

Road Section between Hetauda and Pathlaiya Eroded after landslide in Churiyamai, one way traffic movement is in operation. Gabion wall, Earth filling and gravel works are ongoing.

Access disrupted after one of the pillars of Dudhaura bridge sank on Sunday morning. Heavy loaded vehicles are restricted to pass.

Dhansasr Bridge damaged, one way traffic in operation, Gabion wall, Earth filling and Gravelling work started.

Chandrapur-Gaur road is disrupted, Flood eroded about 40m length of road.

Road section between Dhalkebar and Jaleshwar is closed due to bad road condition

Road between Baitadi-Darchula is blocked by landslides in various places

Dandeldhura-Bajhang road is blocked by landslide

Laharekhola bridge damaged due to Scouring.

Nepalgunj to Bardiya HQ is not operational due to inundation by Babai River

Gandhali Bridge: Approach road/slab collapsed Oneway traffic is in operation

Transportation halted on postal road as 2 km section has been swept away between Kandadhik – Sonafata in Bhajani

FRAME 2

Dharan -Dhankuta road is disrupted by landslides in several places

Dolokha-Jiri road is disrupted by landslides in several places

Paanchtar-Taplejung road is blocked by landslides in several places

Road section between Kathmandu and Hetauda via Dakshinkali is closed due to Landslide

Ratu Bridge collapsed due to flood in Ratu River, one way traffic is allowed to light vehicle, Diversion road open for heavy vehicle

Biratnagar Airport is closed since 11 August, the runway has completely been covered by mud and sand

Road section between Dhalkebar and Bardibas is eroded by flood. One way vehicular movement is in operation

Only one way vehicular movement is allowed between Dhanusadham and Dharapani.Humepipe Swept away by flood water at Kishannagar

One way traffic is in operation between Surunga and Durgapur due to damage in right bank protection work at Kankai river bridge

Biratnagar-Biratchok road is obstructed at Ghinaghat due to damages in the bridge.

FRAME 1

N

0 10 20 40
Kilometers

National Capital
Major Town
Intermediate Town
Small Town
Village

Domestic Airport Closed
International Airport
Domestic Airport
Airstrip

National Highway / Primary Road
Feeder Road / Secondary Road
Postal Road
Other Road
Railway

Obstacle
Road Passable
Damaged but passable
Road Not passable

International Boundary
Region boundary
District Boundary
River
Water Body

**Flood Affected Districts**




Date Created: **17 Aug 2017**
Contact: **hq_im_rome@wfp.org**
Website: **www.logcluster.org**

Prepared by: **biplob.rakhal@wfp.org**
Map Reference: NPL_LC_AccessConstraints_A3L

Data Sources: WFP, LC, UNGIWG, Survey Department of Nepal, GeoNames,DoR, DTMP, RAP,
Information Source: WFP, GIZ, UNDSS

The boundaries and names and the designations used on this map do not imply official endorsement or acceptance by the United Nations.

WFP
wfp.org